Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Reed Henderson AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable **Mine ID:** 613 Map ID: N285 **CERCLIS:** NNN000908921 Navajo Abandoned Mine Land Reclamation Program: None Local name / Aliases: None Chapter and local area: Sanostee Chapter **County:** San Juan **State:** New Mexico **Lat/Long:** 36.3795490479 N / -109.015610489 W **Nearby road and highway:** Indian Route 5010 Local Post Office: Sanostee Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** Fee land State **Subsurface Mineral Rights:** The mineral rights ownership was identified as Indian. **Claim and operator information:** The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Hancock and Hutchinson in 1954. No other historical ownership / lease information was identified in the EPA/AUM database. Number of residential structures within 200 feet of mine: None **Estimated volume of mine waste onsite:**

None

Part II Summary of radiological readings

Highest gamma radiation measurement:

16,803 counts per minute (cpm)

Describe any other radiological measurements:

A total of 1,438 gamma radiation measurements were collected from the mine site, ranging from 4,978 cpm to 16,803 cpm. The measurements are represented in Figures 1 and 2.


Background Locations #1 9,790 cpm

Average background = 9,790 cpm

111 7,770 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



Count:	1438
Minimum:	4978,00000
Maximum:	16803.00000
Sum:	12600472.00000
Mean:	8762.49791
Median:	8746.50000
Standard Deviation:	1835.73323

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

Not	found	in	NAML	RP	Database
1100	Iouiiu		1 11 11 11		Dutubuse

None

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

of any reclamation caps. Note condition of all caps.
Observed reclamation work and status:
Adits None
Waste Piles None
Pits None
Shafts None
Other Debris and Mine Features

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: A vacant log cabin was located approximately 400' southwest of mine

site

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

All measurements near the house were less than 15,000 cpm

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Reed Henderson mine consists of an area of 7,963.03 m². The mine was identified as being operational in 1954. Historical documents showed the operator of the mine as Hancock and Hutchinson in 1954. While operational, the mine had a total reported production volume of 24 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Reed Henderson **Chapter:** Sanostee

Decision Criteria

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? None

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Vacant house 400' southeast of site

Part VI Photos



Photo 1. Vacant cabin southeast of site



Photo 2. Mine site

Part VII Contacts Reports and Information


Name: Stanley Edison (928) 871-6861 Eugene Esplain (928) 871-7331 Title or official role (if any) Navajo EPA Superfund Program Address PO Box 2946, Window Rock, AZ 86515 Information provided <u>Lead Regulatory Agency</u> Title or official role (if any) Address Telephone number_____ Information provided Title or official role (if any) Telephone number_____ Information provided_____ Name

Title or official role (if any)

Telephone number

Information provided______

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Reed Henderson (613)
Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 9,790 cpm








Figure 2 - Gamma Radiation Measurements Reed Henderson (613) Sanostee Chapter, Navajo Nation, Arizona



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



→ General Direction Down-Slope

Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 9,970 cpm

